



PUBLIC WORKS DEPARTMENT (B & R), HARYANA

OFFICE OF THE SUB DIVISIONAL ENGINEER
PROVINCIAL SUB DIVISION NO.-4, GURUGRAM
Email ID:- sdepsd4@gmail.com



No.

1380

Dated

25/4/19

To


The Manager
Rock Ford Convent High School,
Near Sector 10 A ,Gurugram (Haryana).

Subject: - Issue of Building Safety Certificate.

Reference:- Your letter, dated 12.4.2019 addressed to the office of the Executive Engineer, P-2, Gurugram.

The School building site has been inspected by the ASDE incharge on 24.4.2019. From visual inspection, the building seems to be safe. So far as structural sability is concerned, Sh. O.P.Gulati, M/s Design Better , Opp. Golden Factory, Jharsa Road , Sector 31-32 , Gurgaon had issued Stability Certificate dated 26.12.2016and School management is responsible for the same as per Structural Stability Certificate given by him.

DA/Nil



Sub Divisional Engineer,
Provincial Sub Division No.4,
PWD B&R Branch, Gurugram.

Endst No.


Dated

Copy of above is forwarded to Executive Engineer, Provincial Division No.II, PWD B&R Br., Gurugram for information w.r.t. his good office Endst No. 5200 dt. 22.4.2019.

DA/Nil


Sub Divisional Engineer,
Provincial Sub Division No.4,
PWD B&R Branch, Gurugram.


Manager
Rockford Convent High School
Shakti Park, Near Sec-10 A
Gurgaon


Principal
Rockford Convent High School
Aff. to CBSE
Shakti Park, Gurgaon-122000